345



ons

echnologies

hnical Support
66-670-1591
ww.2gig.com

CAUTION
RISK OF ELECTRICAL SHOCK
DO NOT OPEN

EXPLANATION OF GRAPHIC WARNING SYMBOLS

This symbol is intended to alert the user to the presence of un-insulated "dangerous voltage" within the product's enclosure that may be of sufficient magnitude to constitute a risk of electric shock.

✶ ***WARNING! To reduce the risk of fire or electric shock, do not expose this device to rain, water, or wet locations.***

This symbol is intended to alert the user to the presence of important operating and maintenance (Servicing) instructions in the literature accompanying the device.

IMPORTANT SAFETY INSTRUCTIONS

⚠ WARNING ⚠

TO REDUCE THE RISK OF SEVERE INJURY OR DEATH

1. READ AND FOLLOW ALL INSTALLATION INSTRUCTIONS
2. NEVER LET CHILDREN OPERATE, OR PLAY WITH DOOR CONTROLS! KEEP REMOTE CONTROL AWAY FROM CHILDREN!
3. ALWAYS KEEP MOVING DOOR IN SIGHT AND AWAY FROM PEOPLE AND OBJECTS UNTIL IT IS COMPLETELY CLOSED. NO ONE SHOULD CROSS THE PATH OF THE MOVING DOOR.
4. NEVER GO UNDER A STOPPED, PARTIALLY OPEN DOOR.

⚠ CAUTION ⚠

TO REDUCE THE RISK OF ELECTRIC SHOCK, DISCONNECT POWER TO THE RECEPTACLE BEFORE INSTALLING OR REMOVING THE UNIT. WHEN REMOVING RECEPTACLE COVER SCREW, COVER MAY FALL ACROSS PLUG PINS OR RECEPTACLE MAY BECOME DISPLACED. USE ONLY WITH DUPLEX RECEPTACLE HAVING CENTER SCREW. SECURE UNIT IN PLACE BY RECEPTACLE COVER SCREW.

IMPORTANT SAFET

1. Read these instructions.
2. Keep these instructions.
3. Heed all warnings.
4. Follow all instructions
5. Do not use this apparatus near water.
6. Clean only with dry cloth.
7. Do not install near any heat sources such a apparatus (including amplifiers) that produc
8. Do not defeat the safety purpose of the pola plug has two blades with one wider than the blades and a third grounding prong. The wi your safety. If the provided plug does not fit replacement of the obsolete outlet.
9. Unplug this apparatus during lightning storr
10. Refer all servicing to qualified service perso apparatus has been damaged in any way, s damaged, liquid has been spilled or objects has been exposed to rain or moisture, does

COMPONENT LOCATIONS

s designed for use as a radio receiver to with **2GIG-KEY2-345** key fob transmitters IG-KEY1-345 key fobs or any other models ained, not requiring an external transformer The receiver plugs directly into a 120 VAC ecure the receiver to the outlet.

e for connection to the garage operator's "A", relay in the receiver will provide a when the receiver activates.

ontain a typical "coding switch". During tter's code by receiving a signal from the s the transmitter's code into the receiver's ory, even without power. The receiver can ansmitters. The receiver will activate only in the receiver's memory.

are used for entering and erasing the he learn indicator also lights to show RF ting.



DETERMINE THE BEST RECEIVER LOCATION



CHECK FOR INTERFERENCE



IF
W
IN
A

TEST
INTE
OPE

IF TH
OPE

TO R
THE
FRO

THE OPERATOR

DISCONNECT POWER TO THE GARAGE DOOR OPERATOR BEFORE PROCEEDING

UL NOTE: ALL LOW VOLTAGE CLASS 2 CABLE USED WITH THE OPERATOR MUST BE UL LISTED TYPE CL2, CL2P, CL2R, OR CL2X OR OTHER CABLE WITH EQUIVALENT OR BETTER ELECTRICAL, MECHANICAL, AND FLAMMABILITY RATINGS



OR

-GDR1-345
ECEIVER

NALS 1 & 2
RMINALS
ITTON USES)

INSTALL THE RECEIVER



PROGRAM AND TEST THE RECEIVER



ADDING TRANSMITTERS

1. PRESS AND RELEASE THE LEARN BUTTON
2. THE LEARN INDICATOR WILL LIGHT IF THERE'S ROOM IN MEMORY (UP TO 10 TRANSMITTERS WILL FIT, EACH ONE MORE THAN TEN WILL ERASE THE OLDEST TRANSMITTER)
3. ACTIVATE THE TRANSMITTER WHILE THE INDICATOR IS LIT (WITHIN 15 SECONDS) PRESS THE TRANSMITTER'S ✶ BUTTON
4. RECEIVER INDICATOR FLASHES
5. REPEAT STEPS FOR ADDITIONAL TRANSMITTERS

AFTER LEARNING, PRESSING THE ✶ KEY WILL ACTIVATE THE GARAGE DOOR RECEIVER

TEST RECEIVER
ACTIVATE EACH TRANSMITTER AND VERIFY THAT THE RECEIVER AND DOOR OPERATOR ACTIVATES

ERASING TRANSMITTERS

1. PRESS AND HOLD DOWN THE LEARN BUTTON
2. THE LEARN INDICATOR WILL FLASH COUNTING THE NUMBER OF TRANSMITTERS IN MEMORY
3. CONTINUE HOLDING DOWN THE LEARN BUTTON
4. 5 SECONDS AFTER THE COUNT THE INDICATOR WILL FLASH ONCE SHOWING THE MEMORY ERASURE
5. RELEASE THE BUTTON, THE UNIT ENTERS LEARN MODE FOR 15 SECONDS

NOTE: 2GIG-KEY1-345 KEY FOBS ARE NOT COMPATIBLE WITH THIS RECEIVER

2GIG-KEY2-345

LIMITED W

This 2gig Technologies Inc. product is warranted agains months. **This warranty extends only to wholesale** authorized distribution channels. **2gig Technologies I** Consumers should inquire from their selling dealer as t **no obligations or liabilities on the part of 2gig Tech out of or in connection with use or performance of th to loss of property, revenue, or profit, or cost of** warranties, including implied warranties for merchantab until the warranty expires. **This 2gig Technologies Inc. or implied.**

IMPORT

Radio controls provide a reliable communications link ar However, there are some limitations which must be obs

- ✶ For U.S. installations only: The radios are required to comp they have limited transmitter power and therefore limited ra
- ✶ A receiver cannot respond to more than one transmitted si or near their operating frequencies, regardless of code sett
- ✶ Changes or modifications to the device may void FCC com
- ✶ Infrequently used radio links should be tested regularly to
- ✶ A general knowledge of radio and its vagaries should be ga facts should be communicated to the ultimate users.

This device complies with FCC Part 15 and Canada following two conditions: (1) This device may not cause any interference received, including interference that ma

Copyright © 2010